

Product	LivePremier Simulator
Date	April 08 th , 2024
Version	4.00.13

Technical Notes:

Warnings

- do not use LivePremier Simulator and Midra 4K or Alta Simulator simultaneously as erroneous behaviors may be encountered.
- when simulating LivePremier firmware v2.0.228 and above:
 - if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66
- when simulating LivePremier firmware v2.3.103 and above:
 - do not disable both HTTP and HTTPS servers in the Remote Control settings of the device as it will result in the permanent loss of the session

New Feature

- [MacOS] LivePremier firmware v4.00.254 is now supported on MacOS simulator

Evolution

- [Windows] Windows Firewall popup on the first use is now removed

Bug fixes

- Some external variables are now correctly simulated
- 8-plug cards are now correctly limited to HDCP1
- QSFP LEDS are now simulated correctly
- It is now possible to display the list of devices while the session is active



PREVIOUS VERSIONS



Product	LivePremier Simulator
Date	March 20 th , 2024
Version	4.00.11

Technical Notes:

Warnings

- do not use LivePremier Simulator and Midra 4K or Alta Simulator simultaneously as erroneous behaviors may be encountered.
- when simulating LivePremier firmware v2.0.228 and above:
 - if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66
- when simulating LivePremier firmware v2.3.103 and above:
 - o do not disable both HTTP and HTTPS servers in the Remote Control settings of the device as it will result in the permanent loss of the session

New Feature

- [Windows] Supports LivePremier firmware v4.00.254 on Windows
- Ability to simulate up to 4 linked devices
- Ability to select and load older firmware versions

Evolution

Interface update

Bug fixes



Product	LivePremier Simulator
Date	April 17 th , 2023
Version	2.1.2

Technical Notes:

Warnings

do not use LivePremier Simulator and Midra 4K Simulator simultaneously as erroneous behaviors may be encountered.

- when simulating LivePremier firmware v2.0.228 and above:
 - if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66
- when simulating LivePremier firmware v2.3.103 and above:
 - do not disable both HTTP and HTTPS servers in the Remote Control settings of the device as it will result in the permanent loss of the session

New Feature

Supports LivePremier firmware v3.1.78

Evolution

Interface update

Bug fixes



Product	LivePremier Simulator
Date	November 29 th , 2022
Version	2.0.6

Technical Notes:

Warnings

- do not use LivePremier Simulator and Midra 4K Simulator simultaneously as erroneous behaviors may be encountered.
- when simulating LivePremier firmware v2.0.228 and above:
 - if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66
- when simulating LivePremier firmware v2.3.103 and above:
 - o do not disable both HTTP and HTTPS servers in the Remote Control settings of the device as it will result in the permanent loss of the session

New Feature

- Supports LivePremier firmware v3.0.255

Evolution

Interface update

Bug fixes



Prod	uct	LivePremier Simulator
Date		April 19 th , 2022
Vers	ion	1.6.1

Technical Notes:

Warnings

- do not use LivePremier Simulator and Midra 4K Simulator simultaneously as erroneous behaviors may be encountered.
- when simulating LivePremier firmware v2.0.228 and above:
 - o if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66
- when simulating LivePremier firmware v2.3.103 and above:
 - do not disable both HTTP and HTTPS servers in the Remote Control settings of the device as it will result in the permanent loss of the session

New Feature

- Supports LivePremier firmware v2.5.14

Evolution

- None

Bug fixes



Product	LivePremier Simulator
Date	February 22 nd , 2022
Version	1.5.1

Technical Notes:

Warnings

- do not use LivePremier Simulator and Midra 4K Simulator simultaneously as erroneous behaviors may be encountered.
- when simulating LivePremier firmware v2.0.228 and above:
 - if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66
- when simulating LivePremier firmware v2.3.103 and above:
 - do not disable both HTTP and HTTPS servers in the Remote Control settings of the device as it will result in the permanent loss of the session

New Feature

- Supports LivePremier firmware v2.4.27

Evolution

- None

Bug fixes

- In the SETUP>Preconfig>Backgrounds page of the Web RCS, assigning a capacity 2 input to a capacity 1 output now reports an error
- In the LIVE>Screens page of the Web RCS, switching Preset Toggle from On to Off doesn't cause Screen Memory Id problems on Preview anymore.



P	roduct	LivePremier Simulator
D	Pate	November 22 nd , 2021
V	'ersion	1.4.4

.....

Technical Notes:

Warnings

- when simulating LivePremier firmware v2.0.228 and above:
 - if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66
- when simulating LivePremier firmware v2.3.103 and above:
 - o do not disable both HTTP and HTTPS servers in the Remote Control settings of the device as it will result in the permanent loss of the session

New Feature

- Supports LivePremier firmware v2.3.103
- Support of new hardware:
 - o SDVoE input card (ref. AQL-ACC-IN-SDVOE)
 - o SDVoE output card (ref. AQL-ACC-OUT-SDVOE)
 - o Input filler card (ref.AQL-ACC-IN-FILLER)

Evolution

- None

Bug fixes

- A screen without assigned outputs must not appear in the Live page of the Web RCS



Product	LivePremier Simulator
Date	May th , 2021
Version	1.3.0

Technical Notes:

Warning when simulating LivePremier firmware v2.0.228 and above:

- if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66

New Feature

- Supports LivePremier firmware v2.2.79

Evolution

- None

Bug fixes



Pro	duct	LivePremier Simulator
Date	e	March 23 rd , 2021
Vers	sion	1.2.7

Technical Notes:

Warning when simulating LivePremier firmware v2.0.228 and above:

- if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66

New Feature

- None

Evolution

- Add the simulated device a default serial number "ZZ9999" (Useful for AW VideoCompositor for LivePremier and Crestron driver programing)

Bug fixes



Product	LivePremier Simulator
Date	February 24 th , 2021
Version	1.2.6

Technical Notes:

Warning when simulating LivePremier firmware v2.0.228 and above:

- if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66

New Feature

- Supports LivePremier firmware v2.1.82

Evolution

- Audio management and routing support

Bug fixes

- When the first input card is a DisplayPort card, the DPH104 feature is not available



Product	LivePremier Simulator
Date	December 15 th , 2020
Version	1.2.3

Technical Notes:

Warning when simulating LivePremier firmware v2.0.228 and above:

- if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66

New Feature

- Simulation of LivePremier firmware v2.1.73

Evolution

- None.

Bug fixes



Product	LivePremier Simulator
Date	July 30 th , 2020
Version	1.1.8

Technical Notes:

Warning when simulating LivePremier firmware v2.0.228:

- if the Basic Authentication feature is enabled without changing the password, the default password is the MAC address 11:22:33:44:55:66

New Feature

- Simulation of LivePremier firmware v2.0.228
- Generation of ordering numbers for LivePremier's Aquilon C and C+

Evolution

- None.

Bug fixes



Product	LivePremier Simulator
Date	May 18 th , 2020
Version	1.0.6

Technical Notes:

New Feature

- The LivePremier Simulator is now also available for Mac.

Evolution

- None.

Bug fixes

- Working with RC400T can crash the Web RCS server
- Correction on AOI management
- Output capacities may be inconsistent



Product	LivePremier Simulator
Date	April 29 th , 2020
Version	1.00.00

was to stand broken

Technical Notes:

Supported OS

This initial version is only available for Microsoft Windows systems. The Mac OS version will be released later.

Initial published release

- Support for LivePremier series: Aquilon RS alpha, RS1, RS2, RS3, RS4, C and C+
- Simulation of LivePremier firmware v1.2.10
- Customizable I/O card types
- Up to 10 session slots, one session running at a time
- 2 possible input formats depending on input capacity:
 - o Capacity 1: 1920x 1080
 - o Capacity 2: 3840x 2160
- Import/Export of the device configuration using the Web RCS
- Usable with RC400T